

**SECRET**

OUT55940

S E C R E T 111457Z

1965 JUN 11 15 06Z

25X1

1. CAMERA B 101 WAS USED IN MISSION 8022 FLOWN ON 9 JUNE 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

## 2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND RESOLUTION COULD NOT BE DETERMINED.

B. 9R SIDE: THERE WAS A MANUFACTURING SPLICE IN FRAME 214 WITH ASSOCIATED FOG.

C. 9L SIDE: THERE ARE SEVERAL PLUS DENSITY LINES RUNNING PARALLEL TO THE MAJOR AXIS STARTING IN FRAME 20 AND REMAINING THROUGHOUT THE MISSION.

D. BOTH SIDES: THERE ARE EMULSION LIFTS AND BLISTERS INTERMITTENTLY THROUGHOUT THE WHOLE MISSION. ROLLER CHATTER IS PRESENT ALONG INBOARD AND OUTBOARD EDGES THROUGHOUT THE MISSION. THERE WERE 273 FRAMES ON EACH SIDE OF THE MISSION.

## 3. POSITIVE:

A. PI SUTIABILITY WAS POOR DUE TO HEAVY HAZE AND CLOUDS.

B. PRINTING AND PROCESSING WAS ADEQUATE.

C. CLOUD COVER WAS APPROXIMATELY 95 PERCENT.


S E C R E T

-END OF MESSAGE-

11 JUN 1965

COPIES RECEIVED <u>7</u>		
Cy No.	Office	Act.
<u>1</u>	File	
<u>2</u>	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
<u>3,4</u>	TID	<input checked="" type="checkbox"/>
	PID	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

25X1

**SECRET**

Declassification Review by NGA/DoD